

TEMPERATURE CONVERSION CHART (FAHRENHEIT - CENTIGRADE)

°C	C to F ▶ ◀F to C	°F	°C	C to F ▶ ◀F to C	°F	°C	C to F ▶ ◀F to C	°F
-46	-50	-58	21	70	158	138	280	536
-43	-45	-49	24	75	167	143	290	554
-40	-40	-40	27	80	176	149	300	572
-35	-30	-22	29	85	185	154	310	590
-32	-25	-13	32	90	194	160	320	608
-29	-20	-4	35	95	203	166	330	626
-26	-15	+5	38	100	212	171	340	644
-23	-10	14	43	110	230	177	350	662
-21	-5	23	49	120	248	182	360	680
-18	0	32	54	130	266	188	370	698
-15	+5	41	60	140	284	193	380	716
-12	10	50	66	150	302	199	390	735
-10	15	59	71	160	320	204	400	752
-7	20	68	77	170	338	210	410	770
-4	25	77	82	180	356	216	420	788
-1	30	86	88	190	374	221	430	806
0	32	90	99	210	410	227	440	824
+2	35	95	100	212	414	232	450	842
5	40	104	104	220	428	238	460	860
7	45	113	110	230	446	243	470	878
10	50	122	116	240	464	249	480	896
13	55	131	121	250	482	254	490	914
16	60	140	127	260	500	260	500	932
18	65	149	132	270	518			

How to Use this Table

Locate the temperature in the middle column and read the equivalent °F in the right hand column and the equivalent °C in the left hand column.

Example

1. °C to °F: You wish to convert 40°C to °F. Locate 40 in the bold typeface column and read the appropriate temperature in the °F column to the right. The answer is 104°F.
2. °F to °C: To convert 40°F to °C, locate 40 in the bold typeface column, and the °C column to the left will show that the answer is 5°C.